



If the CMM quality control is your bottle neck.....



.....we have the solution
OUR FULLY AUTOMATED 3D MEASURING MACHINE



OPTICAL TOUCH SYSTEMS
FOR CONTACTLESS 3D



The control strategy:

- ✚ Acquire millions of points on the component, rapidly and without touching it.
- ✚ Superimpose the resulting scan on the native 3D CAD model
- ✚ Obtain the deviation analysis for the entire object



- ✚ The acquisitions and controls may be carried out at either our premises or the customer's
- ✚ Accurate analysis of soft and flexible objects

